PROJECT ID:

Roofing

SCOPE:

ESTIMATION

CLIENT'S INFORMATION:

CONTACT: www.usaestimation.com

E-MAIL ADDRESS: info@usaestimation.com

PHONE NUMBER:

Date: 08/28/2023

| | | | Date: 08/28/2 | | | | | | ί,3 |
|-------------|--------------|---|--|--|--|------------------|-------------|--|---------------------|
| ITEM # | DWG.# | DESCRIPTION | QUANTITY | UNIT | MATERIAL | LABOR | UNIT COST | TOTAL COST | TRADE COST |
| | | GENERAL REQUIREMENTS | | | | | | | |
| 1 | | Supervision | 1 | LS | | | \$0 | \$0 | |
| 2 | | Permits | 1 | LS | | | \$0 | \$0 | |
| 3 | | Final Clean-up | 1 | LS | | · | \$0 | \$0 | 1 |
| 4 | | Mobilization Costs | 1 | LS | + | ' | \$0 \$0 | \$0 \$0 | |
| 5 | | | 1 | LS | + | 1 | | \$0 \$0 | 1 |
| - | | Project Overheads | 1 | | | '—— | \$0 \$0 | · · | · |
| 6 | | Bonds | 1 | LS | + + | 1 | \$0 \$0 | \$0 \$0 | 1 |
| 7 | | Temporary Control & Facilities | 1 | LS | | 1 | \$0 | \$0 | |
| | | Subtotal (General Requirements) | | ! | | | | | <u>\$0</u> |
| | | | | | | | | | |
| | | DIVISION 07- THERMAL & MOISTURE PROTECTION | | | | | | | |
| | | | | | | | | | |
| igsquare | | Roofing | | | \Box | | | | |
| 8 | A2.2 | TPO 60 MIL Roof Membrane | 51898 | SF | \$1.8 | \$1.2 | \$3 | \$155,693 | |
| J | . 1216 | -Manuf.: Firestone | 22000 | | ٠.٠٠ | 7 - 1 - 2 | | , _JJJJJ | |
| 9 | A2.2 | TPO 60 MIL Roof Membrane (L=5'-0") | 282 | SF | \$3.5 | \$2.5 | \$6 | \$1,694 | , |
| | v Bis | -Manuf.: Firestone | | 1 | , | | | , _,oo-r | |
| 10 | A2.2 | TPO 60 MIL Roof Membrane (L=5'-6") | 369 | SF | \$3.5 | \$2.5 | \$6 | \$2,211 | · |
| | - | -Manuf.: Firestone | + | ! | + + | 1 | | | |
| 11 | A2.2 | TPO 60 MIL Roof Membrane | 176 | SF | \$3.5 | \$2.5 | \$6 | \$1,056 | 1 |
| | | -Manuf.: Firestone TPO 60 MIL Roof Membrane (I=10'-0") | | <u> </u> | | | | | 1 |
| 12 | A2.2 | TPO 60 MIL Roof Membrane (L=10'-0") | 549 | SF | \$3.5 | \$2.5 | \$6 | \$3,296 | · |
| \vdash | | -Manuf. : Firestone TPO 60 MIL Roof Membrane (L=2'-2") | + | | | | | | 1 |
| 13 | A2.2 | | 817 | SF | \$3.5 | \$2.5 | \$6 | \$4,900 | 1 |
| | | -Manuf. : Firestone TPO 60 MIL Roof Membrane (L=1'-10") | | | | | · | | 1 |
| 14 | A2.2 | TPO 60 MIL Roof Membrane (L=1'-10") -Manuf. : Firestone | 105 | SF | \$3.5 | \$2.5 | \$6 | \$633 | 1 |
| | | | | <u> </u> | + | | | | |
| | | Insulation | | , | + | | | | <u> </u> |
| 15 | A2.2 | R-16 Rigid Insulation | 51898 | SF | \$0.6 | \$0.4 | \$1 | \$51,898 | <u> </u> |
| | | <u> </u> | | <u> </u> | 70.0 | , ∪. → | 7- | , = =,000 | , — |
| | | Gutter & Downspouts | | 1 | 1 | - | | | - |
| 16 | A2.2 | 6"x8" Gutter | 396 | LF | \$4 | \$3 | \$7 | \$2,770 | |
| 17 | A3.0 | 3-1/2"x5" Downspout | 332 | LF | \$3 | \$2 | \$5 | \$1,661 | |
| | | | | · | | | | | |
| | | Coping & Blocking | | | | | | | |
| 18 | A2.2 | (4) 2x8 Nailers | 1583 | LF | \$10 | \$6 | \$16 | \$25,322 | |
| 19 | A2.2 | 2x8 Treated Blocking | 104 | LF | \$2.5 | \$1.5 | \$4 | \$415 | |
| 20 | A2.2 | 8" Wide Aluminum Coping W/ Edge Stripping On Both Sides | 499 | LF | \$20 | \$10 | \$30 | \$14,983 | |
| 21 | A2.2 | 2x10 Treated Wood Blocking | 413 | LF | \$3 | \$2 | \$5 | \$2,066 | |
| 22 | A2.2 | 30" Wide Aluminum Coping W/ Edge Stripping On Both Sides | 17 | LF | \$20 | \$10 | \$30 | \$516 | , |
| | | | | · | 720 | 7.10 | | 7010 | 1 |
| 23 | A2.2 | 10" Wide Aluminum Coping W/ Edge Stripping On Both Sides | 509 | LF | \$20 | \$10 | \$30 | \$15,256 | ' 7 |
| | | | | <u> </u> | , | , | , | ,_50 | 1 |
| | | en i i i i e e e | 1 | ! | + + | 1 | | | 1 |
| ~ . | | Flashing & Trims | F | · - | - | 60 | | ¢2 === | 1 |
| 24 | A2.2 | Counter Flashing Or Roof To Wall Flashing @ Parapet Base | 541 | LF | \$3 | \$2 | \$5 | \$2,705 | 1 |
| 25 | A2.2 | Cover) | 629 | LF | \$3 | \$2 | \$5 | \$3,147 | 1 |
| | A2.2 | Cover) Metal Flashing | 60 | LF | \$3 | \$2 | \$5 | \$298 | · |
| 26 27 | A2.2 A2.2 | Metal Flashing Reglet Counter Flashing | 60 | LF LF | \$3 \$3 | \$2 \$2 | \$5 \$5 | \$298 \$298 | |
| 27 | A2.2 A2.2 | Reglet Counter Flashing 24 GA. Edge Trim | 60 | LF LF | \$3 \$1.9 | \$2 \$1.1 | \$5 \$3 | \$298 \$188 | |
| 28 | A2.2 A2.2 | 24 GA. Edge Trim Flashing At Low Ridge | 121 | LF LF | \$1.9 | \$1.1 | \$3 \$5 | \$188 | |
| | , 15.E | | 121 | <u></u> | د د | 74 | ٠,٠ | Ç00 -1 | <u> </u> |
| | | Sealants | | , | + | | | | <u> </u> |
| 30 | A2.2 | Tooled Sealant | 60 | LF | \$1.1 | \$0.9 | \$2 | \$119 | · |
| 31 | A2.2 A2.2 | Sealant/Flashing @ Roof Equipment | 177 | LF LF | \$1.1 | \$0.9 | \$2 \$2 | \$119 | |
| 94 | | , | | | 7 | 70.0 | 7- | ,557 <u>-</u> 7 | <u> </u> |
| 1 | | Roof Fence | | , | † † | | | | · |
| | | 6'-0" H Roof Screen Chainlink Fence W/ Closed PolyFence Privacy | _ | . | 1 . | - | - · | 4 | , |
| 32 | A2.2 | Screen | 566 | LF | \$20 | \$10 | \$30 | \$16,989 | · |
| 33 | A2.2 | 3'-0" Wide Fence Gate | 6 | EA | \$450 | \$250 | \$700 | \$4,200 | |
| | | <u> </u> | | · . | T | | | | |
| | | Subtotal (Thermal & Moisture Protection) | 1 | | † | · | 1 | | \$313,269 |
| | | - Custostal (Thermal & Moistale Flotection) | <u> </u> | <u> </u> | | | | <u>. </u> | 7313,203 |

PROJECT ID:

Roofing

SCOPE:

ESTIMATION

CLIENT'S INFORMATION:

CONTACT: www.usaestimation.com

E-MAIL ADDRESS: info@usaestimation.com

PHONE NUMBER:

Date: 08/28/2023

| ITEM# | DWG.# | DESCRIPTION | QUANTITY | UNIT | MATERIAL | LABOR | UNIT COST | TOTAL COST | TRADE COST |
|----------|---------|-------------|----------|------|----------|-------|-----------|------------|--------------|
| SUBTO | DTAL | | | | | | | | \$313,268.82 |
| OVERH | HEAD | 15 | 5% | | | | | | \$46,990.32 |
| INSURA | ANCE | 3 | 1% | | | | | | \$9,398.06 |
| CONTING | GENCY | 5 | 3% | | | | | | \$15,663.44 |
| TOTAL BA | ASE BID | | | | | | | | \$385,320.65 |
| Note: | | | | | | | | | |